

Questions & Answers
OConnor Oil Co Bulk Plant
COMM #54901-1201-05
BRRTS #02-71-259386

Question: How many wells need to be abandoned and does that cost need to be included on the bid table in the bid response?

Answer: There will be a total of 10 wells that need to be abandoned. They are on average about 15 feet deep. The cost for the abandonment must be included in the bid table under a separate line item. (I apologize for not creating a separate line item for this task.) If a bidder inadvertently excludes this cost from the table, I will make a phone call to verify the final bid amount.